

Box Hill—South Tributary
June 2009



Upstream from Sta 11+00



Downstream from Sta 10+75



Downstream from Sta 10+20



Downstream from Sta 09+25



Downstream from Sta 08+75



Downstream from Sta 08+60



Downstream from Sta 08+00



Downstream from Sta 07+75



Downstream from Sta 07+30



Upstream from Sta 06+10



Downstream from Sta 05+50



Downstream from Sta 04+40

Box Hill—South Tributary
October 2009



Upstream from Sta 11+25



Downstream from Sta 10+85



Downstream from Sta 10+20



Downstream from Sta 09+50



Downstream from Sta 08+65



Downstream from Sta 08+60



Downstream from Sta 08+00



Downstream from Sta 07+75



Downstream from Sta 07+30



Upstream from Sta 06+10



Downstream from Sta 05+50



Downstream from Sta 04+25

Box Hill—South Tributary
May 2010



Upstream from Sta 11+00



Downstream from Sta 10+75



Downstream from Sta 10+20



Downstream from Sta 09+25



Downstream from Sta 08+60



Downstream from Sta 08+60



Downstream from Sta 08+00



Downstream from Sta 07+75



Downstream from Sta 07+30



Upstream from Sta 06+10



Downstream from Sta 05+50



Downstream from Sta 04+40

Box Hill—South Tributary
November 2010



Upstream from Sta 11+00



Downstream from Sta 10+75



Downstream from Sta 10+20



Upstream from Sta 09+50



Downstream from Sta 08+60



Downstream from Sta 08+50



Downstream from Sta 08+00



Downstream from Sta 07+75



Downstream from Sta 07+30



Downstream from Sta 06+10



Downstream from Sta 05+50



Downstream from Sta 04+40

Box Hill—South Tributary
October 2011



Upstream from Sta 11+00



Downstream from Sta 10+50



Downstream from Sta 10+20



Downstream from Sta 09+50



Downstream from Sta 08+75



Downstream from Sta 08+50



Downstream from Sta 08+00



Downstream from Sta 07+75



Downstream from Sta 06+75



Downstream from Sta 06+10



Downstream from Sta 05+50



Downstream from Sta 04+40